



HW

MAN

n 6400 - 11100

| D   | B  | d  | Z | €   |
|-----|----|----|---|-----|
| 120 | 40 | 30 | 2 | 305 |

